

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
NY
25-HARV
1-

ALPINA IRON FURNACE
At the head of Bonaparte Creek
Harrisville Vicinity
Lewis County
New York

HAER No. NY-188

Photographer: Rob Tucher

May 1988

- NY-188-1 ALPINA FURNACE, EAST (TUYERE) ELEVATION, VIEW LOOKING WEST.
- NY-188-2 ALPINA FURNACE, VIEW LOOKING NORTHEAST TOWARD SOUTH (CHARGING) ELEVATION.
- NY-188-3 ALPINA FURNACE, VIEW LOOKING SOUTHWEST.
- NY-188-4 ALPINA FURNACE, VIEW LOOKING EAST.
- NY-188-5 ALPINA FURNACE, VIEW LOOKING SOUTH-SOUTHEAST.
- NY-188-6 ALPINA FURNACE, VIEW FROM TRUNCATED TOP SHOWING OUTER (STONE) AND INNER (BRICK) WALLS.
- NY-188-7 ALPINA FURNACE, INTERIOR VIEW LOOKING SOUTH.
- NY-188-8 VIEW LOOKING NORTHWEST TOWARD UPSTREAM SIDE OF STONE DAM AT LOWER END OF MUD LAKE; AT RIGHT IS SPILLWAY.
- NY-188-9 VIEW LOOKING SOUTH TOWARD STONE DAM AND SPILLWAY. STONE FOOTINGS AT CENTER AND FRONT. SPILLWAY OF 1933 CONCRETE DAM AT UPPER RIGHT REAR.
- NY-188-10 VIEW LOOKING NORTHWEST TOWARD SAWMILL SITE; STONE FOOTINGS IN CENTER AND LEFT FOREGROUND.
- NY-188-11 VIEW LOOKING SOUTH TOWARD SAWMILL SITE, SHOWING STONE WALLS FORMING THREE CHANNELS PRESUMED TO BE WHEEL PITS.
- NY-188-12 VIEW LOOKING SOUTH AT CONCRETE SLUICeway WHICH CONTROLS FLOW OF SECONDARY CHANNEL OF BONAPARTE CREEK, DOWNSTREAM FROM THE SPILLWAY OF THE 1933 DAM.